

# DeSoto Parks and Recreation

## Moseley Pool Chemical Log F2025-5427715

Type : Form

User Type : User

Date & Time : 7/25/2025 2:04 PM

Name : PublicDesoto

Instructions : Review and customize this form to meet your needs.

| Question                                                             | Response     |
|----------------------------------------------------------------------|--------------|
| Date of Reading                                                      | 07.25.2025   |
| Time of Reading                                                      | 2:02 PM      |
| Staff Member Taking Reading                                          | Matthew Reed |
| Water Check - Free Chlorine (1.5 - 3.0 ppm)                          | 1.0          |
| pH Test (7.2 - 7.8)                                                  | 7.5          |
| Total Chlorine = FC + CC                                             |              |
| Cyanuric Acid (30-50 ppm)                                            |              |
| Total Alkalinity (80-120 PPM)                                        |              |
| Calcium Hardness (200-400 PPM)                                       |              |
| Flow Rate                                                            | 1            |
| ORP                                                                  | 665          |
| Water Temperature (F)                                                | 81           |
| Air Temperature (F)                                                  | 95           |
| Saturation Index                                                     |              |
| Water Clarity                                                        | Great        |
| Influent Pressure                                                    | 27           |
| Effluent Pressure                                                    | 12           |
| Pressure Differential                                                | 15           |
| Chemicals and Amounts Added (Opening or Close)                       |              |
| Were any calibrations made? If yes, what was the calibration set as? |              |
| Any other notes/comments                                             | Shallow area |
| Notified AD/MAA or maintenance? If yes, who?                         |              |